
Esgobaeth Bangor
The Diocese of Bangor

Yr Eglwys yng Nghymru
The Church in Wales

St Mary Church, Llanfair-yng-Nghornwy – Grade I

Prepared by Bethan Jones Swyddog Eiddo Archddiaconiaeth | Archdeaconry Property Officer


Investigative works to timbers and valley













14.08.25 investigation, 9:30, heavy downpoor allowed us to see water dripping. (sample of wood in box).
In yellow there is a pound coin size hole.





