Key

Item 3.01 - 3.04 Refer to Schedule of Works (Raking out and repointing in two stages)

Item 3.08 Carefully lift existing copings. Set aside. Inspect with C.A.
Item 3.09 Allow to install new code 6 lead DPC below copings, lapped over existing weathering to kneeler stone and under weathering adjacent to bellcote all to LSTA details as schedule of works.



Reference Plan Not to Scale

Item 3.06 Carefully remove existing vegetation. All **Item 3.04** fully repoint/coping stones in hot lime mortar as specification.

Item 3.15 Allow provisional sum for conservation of headstock whilst access is available

Item 3.14 Provide new weathering to bell wire Load slate coursed-in to slate, with welded (off-site) spigot. Allow to adjust bell wire and slate and fully reinstate on completion. All details as LSTA and schedule of works

Item 4.01 Isolated slate repairs as schedule of works

01 West Gable Interior Elevation - As Existing 1:50 @ A3



Item 3.11 Provide high level access to inspect corroding iron finial.
Allow provisional sum for conservation and repair as schedule of works.
Item 3.16 allow to decorate finial in specialist metal paint as schedule of works

Item 3.15 Allow provisional sum for conservation of headstock whilst access is available

Existing lead weathering to base of bellcote to remain in situ

Item 3.07 Carefully remove both iron fixings (corroding) and make good

Item 3.05 Pointing to extend to glazing line. Allow to remove protective mesh and reinstate with new stainless steel (Austenitic Grade B16) fixings.

02 West Gable Exterior Elevation - As Existing 1:50 @ A3

PROJECT	ST. RHEDYW'S, LLANLLYFNI
JOB NUMBER	BDSR.01
DRAWING TITLE	WEST GABLE INTERIOR AND EXTERIOR ELEVATIONS SHOWING REPAIRS
DRAWING STATUS	TENDER
DRAWING NO.	001
REVISION	-
SIZE & SCALE	1:50 @ A3
First Issue	MAY 26

© Chambers Conservation Ltd
jennifer@chambersconservation.com
rob@chambersconservation.com
07484 133270 or 07919 300428
www.chambersconservation.com

Registered in England and Wales, no. 09787239
Registered address: Mercury House, High Street, Tattenhall, Chester CH3 9PX
Do not scale from this drawing unless agreed

CHAMBERS
ARCHITECTURE · CONSERVATION