



St. Beuno, Clynnog Fawr

Report 02: Photos – South & north transept, and southwest nave ceiling investigations (with mobile boom-lift for access). Dated May 2023.

1. a	<p>South transept photos from Ground level – taken from Crossing.</p>  A photograph showing the interior of the south transept. A red mobile boom-lift is extended towards the ceiling. The ceiling is made of dark wooden beams. A large Gothic window with multiple panes is visible. The walls are light-colored and show signs of wear.
2. a	<p>Window W05</p>  A close-up photograph of window W05, a large Gothic window with multiple panes. The window is set in a stone frame. The walls around the window are light-colored and show signs of wear.

3. Ceiling level photos from lift (looking to south-west corner of south transept)

a



b



c



d



e



4. Window W05 from lift

a



b



5. Ceiling level photos from lift (looking to south-east corner of south transept)

a





d		
6. Ceiling level photos from lift (looking to top of east wall, at roof timber joist ends in south transept)		
a		
b		

7. Window W05 from lift – Detail: Cill and base of mullions (internal view)

a



b



8. North transept photos from lift at ceiling level – looking down to Crossing.

a



9. Ceiling level photos from lift (looking to north-east corner of north transept)

a



b





e



f



8



10 Ceiling level photos from lift (looking to north-west corner of north transept)

a



b



11 Nave photos from lift at ceiling level – looking down to east of nave.

a



12 Ground level photo from nave (looking to south-west corner)

a



13 Ceiling level photos from lift (looking to south-west corner of nave)

a



b



c



14 Other timber uprights to the south-west of the nave.

a



15 Timber ceiling bosses, purlins and upright post – view looking to the south-west corner of the nave.

a



16 Purlin connection (detail).

a



b Purlin connection (wider view, looking to south-west corner).

b



17 Timber ceiling bosses, purlins and upright post – view looking to the north-west corner of the nave.



18 Ceiling level photos from lift (looking to north-west corner of nave)

a





19 Loose central boss that was removed from west of nave.

a



b

