
**St Mary church, Llanfair-yng-Nghornwy – Grade I**
**2026 – 015327 – Roof slope and internal slope *code**
Prepared by Bethan Jones Swyddog Eiddo Archddiaconiaeth | Archdeaconry Property Officer

**Chancel roof & ceiling**

N2



S2




N2 – Missing and slipped slates..



S2





S2

N3

South chapel roof



S3

| **Internal ceiling finishes.** | | |
|---|---|---|
| | | |
| **N2 Timber battens and plaster** | |  |
| **S2 Lath and plaster** | |  |

| | | |
|---|---|---|
| **N3 & S3 Boarded ceiling** | |  |